

Village of Bingham Farms Water Supply System

The Oakland County Water Resources Commissioner (WRC) is pleased to report that the Village of Bingham Farms' water supply system has no known or expected lead service line materials contained within the system. The WRC conducted a Distribution System Materials Inventory (DSMI) as required by the Michigan Department of Environment, Great Lakes, and Energy (EGLE). The inventory concluded that all 363 service lines connected to the Village of Bingham Farms water supply system are comprised of primarily copper piping.

When the Bingham Farms water system was constructed in 1971, the Oakland County engineering requirements permitted only copper service line materials be used to connect a residence to the water main. Several sources of information were reviewed in preparing the Distribution System Materials Inventory, such as; water main plan dates, water main tap dates, tap material on record, tap permits, historic engineering regulations and reports, and water system inspections.

